

Summary of Facility Information in the County of Valley

Owner Name and Address: Rock Creek Marina and Assoc PO Box 883 Glendive MT 59330 Phone: (406) 774-3322

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------|-------------------------|---------------|-------|----------------|
| 2911049 | Rock Creek Marina | 652 S Rock Creek Road | Fort Peck | 59223 | (406) 485-2560 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|-------------------|---|---|--------------|--|--|--------|
| 2 / 02 Currently in Use | 1846 | 5/1/1991 15 / No | Gasoline 4,000 | STI-P3 None | Fiberglass Reinforced Plastic Cathodically Protected | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I J K <input checked="" type="radio"/></div> </div> | <div> <div>Yes</div> <div>Yes Yes Yes</div> </div> | Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: US Army Corps of Engineers PO Box 208 Fort Peck MT 59223 Phone: (406) 526-3411

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------------------|-------------------------|---------------|-------|----------------|
| 5304612 | US Army Corps of Engineers Fort Peck | Judith Road | Fort Peck | 59223 | (406) 526-3411 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|--|--|-------------|--|-------------------------|
| 2 / 10 Currently in Use | 2156 | 6/1/1990 16 / No | Diesel 2,500 | STI-P3 Double-Walled | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 08 Currently in Use | 2154 | 6/1/1990 16 / No | Gasoline 9,000 | STI-P3 Double-Walled | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |
| 8 / 09 Currently in Use | 2155 | 6/1/1990 16 / No | Diesel 2,500 | STI-P3 Double-Walled | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> <div>B <input checked="" type="radio"/> E F <input checked="" type="radio"/> H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Fort Peck Assiniboine & Sioux Tribes
PO Box 1027 Poplar MT 59255 Phone: (406) 768-5155

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------|-------------------------|---------------|-------|----------------|
| 5613890 | Nakoda Trailstop | Main St & 2nd St | Frazer | 59225 | (406) 768-3480 |

| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met |
|-------------------|-----------|-----------|----------|----------------------------|------------------|--------------|--------------------------|---------------|
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C |
| 1 / 01 | | 12/1/1997 | Diesel | Polyethylene Tank Jacket | Flexible Plastic | Safe Suction | A B C D E F G H I J K L | Yes |
| Currently In Use | | 08 / No | 1,000 | None | Double-Walled | | B D E F G H I J K L | Yes Yes Yes |
| 2 / 02 | | 12/1/1997 | Gasoline | Polyethylene Tank Jacket | Flexible Plastic | Safe Suction | A B C D E F G H I J K L | Yes |
| Currently In Use | | 08 / No | 2,000 | None | Double-Walled | | B D E F G H I J K L | Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Grain Growers Oil Co PO Box 847 Scobey MT 59263 Phone: (406) 487-2741

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------|-----------------------------|---------------|-------|----------------|
| 5303160 | Grain Growers Oil Co | 430 1st Ave N PO Box 847 | Glasgow | 59230 | (406) 228-4641 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|---------------------------------------|----------------------------------|--|----------------------------------|----------------------------------|----------------------------------|----------------------------------|---|---|---|---|---|---|---|---|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|----------------------------------|--------------------|
| Status | | | | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 / 05 Currently in Use | 1574 | 5/1/1991 15 / No | Gasoline 8,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently in Use | 1575 | 5/1/1991 15 / No | Gasoline 8,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 7 / 08 Currently in Use | 1577 | 5/1/1991 15 / No | Diesel 6,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 8 / 09 Currently in Use | 1578 | 5/1/1991 15 / No | Diesel 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |
| 9 / 07 Currently in Use | 1576 | 5/1/1991 15 / No | Gasoline 8,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td><td><input checked="" type="radio"/></td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Valley County Airport Commission 501 Court Sq Ste 14 Glasgow MT 59230 Phone: (406) 228-8221

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-------------------------------|-------------------------|---------------|-------|----------------|
| 5303271 | Glasgow International Airport | 100 Airport Road | Glasgow | 59230 | (406) 228-4023 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|--------------------|---|---------------------------------------|--------------|--|-------------------------|
| 2 / 01 Currently in Use | 2726 | 1/1/1980 26 / No | Gasoline 12,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |
| 3 / 02 Currently in Use | 2727 | 4/7/1981 25 / No | Other 12,000 | Cathodically Protected Steel Lined Interior/Impressed Curr | No Piping None | U.S. Suction | <div> <div>A B C D E F G H I J K L</div> <div> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Frances Mahon Deaconess Hospital 621 3rd St S Glasgow MT 59230 Phone: (406) 228-4351

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|----------------------------------|-------------------------|---------------|-------|----------------|
| 5305192 | Frances Mahon Deaconess Hospital | 621 3rd St S | Glasgow | 59230 | |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction | Piping Material | | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|----------------------------------|----------------------|----------------------------------|---|-----------------------------------|----------------------------------|---|---------------|----------------------------------|----------------------------------|----------------------------------|---|---|----------------------------------|---|---|---|---|---|---|--|---|---|---|----------------------------------|---|---|---|---|----------------------------------|--|--------------------|
| Status | | | | Secondary Option | Secondary Option | Piping Type | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 2 / 03 Currently in Use | 1118 | 10/1/1995 10 / No | Diesel 4,000 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | U.S. Suction | <table><tr><td>A</td><td><input checked="" type="radio"/></td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td></tr></table> | A | <input checked="" type="radio"/> | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | Yes Yes Yes Yes |
| A | <input checked="" type="radio"/> | C | <input checked="" type="radio"/> | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |
| 3 / 04 Currently in Use | 1119 | 10/1/1995 10 / No | Diesel 2,000 | Polyethylene Tank Jacket Double-Walled | Flexible Plastic Double-Walled | U.S. Suction | <table><tr><td>A</td><td><input checked="" type="radio"/></td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>B</td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td><input checked="" type="radio"/></td><td></td></tr></table> | A | <input checked="" type="radio"/> | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | D | E | F | G | H | I | J | K | <input checked="" type="radio"/> | | Yes Yes Yes Yes |
| A | <input checked="" type="radio"/> | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | D | E | F | G | H | I | J | K | <input checked="" type="radio"/> | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Jodys Conoco PO Box 232 Glasgow MT 59230 Phone: (406) 228-2313

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------|-------------------------|---------------|-------|----------------|
| 5305709 | Jodys Conoco | 204 1st AVE N | Glasgow | 59230 | (406) 228-2313 |

| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|-----------|---------------------|----------------------------------|---------------------------------------|-----------------------------------|-------------|---|---------------|---|---|----------------------------------|---|---|---|---|---|---|---|---|---|--|--|---|--|---|---|----------------------------------|---|---|---|---|---|--------------------|
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | Piping Type | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | | |
| 5 / 05 Currently In Use | 4201 | 6/1/2000 06 / No | Gasoline 6,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |
| B | | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 6 / 06 Currently In Use | 4202 | 6/1/2000 06 / No | Gasoline 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td colspan="2">D</td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |
| B | | | D | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Wayne Waarvik HC 71 1142 Glasgow MT 59230 Phone: (406) 228-9528

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------------|-------------------------|---------------|-------|----------------|
| 5307787 | Trailside General Store Glasgow | 740 US Highway 2 E | Glasgow | 59230 | (406) 228-9528 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|----------------------------------|-----------|----------------------|---------------------|--|---------------------------------------|-------------|--|-------------------------|
| 3 / 03 Temporarily Out of Use | 3873 | 9/9/1991 14 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |
| 4 / 04 Temporarily Out of Use | 3874 | 9/9/1991 14 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Fiberglass Reinforced Plastic None | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div> <input checked="" type="radio"/> <input checked="" type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> <input type="radio"/> </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Gene Moore HC 71 Box 1660 Glasgow MT 59230 Phone: (406) 526-3597

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------------|-------------------------|---------------|-------|----------------|
| 5308383 | Lakeridge Motel & Tackle Inc | HC 71 Box 1660 | Glasgow | 59230 | (406) 526-3597 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|---------------------|--|---------------------------------------|--------------|--|-------------------------|
| 5 / 05 Currently In Use | 1509 | 5/15/1997 09 / No | Gasoline 4,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently In Use | 1510 | 5/15/1997 09 / No | Gasoline 2,000 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------|-------------------------|---------------|-------|----------------|
| 5309712 | Holiday Stationstore 281 | 108 1st Ave N | Glasgow | 59230 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|----------------------|--------------------|--|---------------------------------------|-------------|---|-------------------------|
| 2 / 04 Currently in Use | 4431 | 8/1/1989 16 / No | Gasoline 8,000 | STI-P3 None | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C D E F G H J K L</div> <div> <input checked="" type="radio"/> <input type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 3 / 01 Currently in Use | 4432 | 3/1/1986 20 / No | Gasoline 12,000 | STI-P3 None | Galvanized Steel Impressed Current | Pressurized | <div> <div>A B C D E F G H J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |
| 5 / 03 Currently in Use | 4433 | 4/15/1988 18 / No | Gasoline 10,000 | STI-P3 None | Bare Steel Impressed Current | Pressurized | <div> <div>A B C D E F G H J K L</div> <div> <input type="radio"/> <input checked="" type="radio"/> E F G H I J K L </div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Ezzies Wholesale Inc PO Box 1770 Malta MT 59538 Phone: (406) 654-2331

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|--------------------------|-------------------------|---------------|-------|----------------|
| 5310475 | Ezzies Wholesale Glasgow | 1330 US Highway 2 W | Glasgow | 59230 | (406) 228-2713 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction | Piping Material | Piping Type | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------------|-----------|----------------------------------|----------------------------------|---------------------------------------|-----------------------------------|----------------------------------|---|---------------|----------------------------------|---|----------------------------------|---|---|---|---|---|---|---|---|---|--|----------------------------------|--|---|---|----------------------------------|---|---|----------------------------------|---|---|--------------------|
| Status | | | | Secondary Option | Secondary Option | | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 7 / 07 Currently In Use | 4758 | 11/21/2002 03 / No | Diesel 12,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 8 / 08 Currently In Use | 4759 | 11/21/2002 03 / No | Diesel 6,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 9 / 09 Currently In Use | 4760 | 11/21/2002 03 / No | Diesel 6,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 10 / 10 Currently In Use | 4761 | 11/21/2002 03 / No | Gasoline 8,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 11 / 11 Currently In Use | 4762 | 11/21/2002 03 / No | Other 4,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Safe Suction | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | <input checked="" type="radio"/> | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | <input checked="" type="radio"/> | K | L | | | | | | | | | | | | | | | | | | | | | |
| 12 / 12 Currently In Use | 4763 | 11/21/2002 03 / No | Gasoline 10,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 13 / 13 Currently In Use | 4764 | 11/21/2002 03 / No | Gasoline 20,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| 14 / 14 Currently In Use | 4765 | 11/21/2002 03 / No | Diesel 30,000 | Fiberglass Reinforced Plastic None | Flexible Plastic Double-Walled | Pressurized | <table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td colspan="2"><input checked="" type="radio"/></td><td>E</td><td>F</td><td><input checked="" type="radio"/></td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table> | A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | Yes Yes Yes Yes |
| A | B | C | <input checked="" type="radio"/> | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |
| B | | <input checked="" type="radio"/> | | E | F | <input checked="" type="radio"/> | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: US Army Corps of Engineers 215 N 17th St Omaha NE 68102 Phone: () -

| | | | | | |
|------------------|-----------------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5313656 | Glasgow Army Air Force Base | | Glasgow | 59230 | |

| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--------------------------|------------------|------------------|-----------------|-----------------------------------|-------------------------|--|----------------------|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|--|--|-----------------|
| TankID/Alt TankID | Tag Numbe | Installed | Product | Tank Mat'l of Construction | Piping Material | Tank Release Detection | FR Met | | | | | | | | | | | | | | | | | | | | | | | | |
| Status | | Age/AST | Capacity | Secondary Option | Secondary Option | Piping Release Detection | Spill/Overl/C | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 / Currently in Use | 0 | | | | | <table border="1" style="width: 100%; text-align: center;"> <tr> <td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td> </tr> <tr> <td>B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td><td></td><td></td> </tr> </table> | A | B | C | D | E | F | G | H | I | J | K | L | B | D | E | F | G | H | I | J | K | L | | | Yes No No No |
| A | B | C | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | |
| B | D | E | F | G | H | I | J | K | L | | | | | | | | | | | | | | | | | | | | | | |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Swanson Brothers Rentals PO Box 1071 Glasgow MT 59230 Phone: (406) 228-2496

| | | | | | |
|------------------|----------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 5613815 | Hanson Mersen Motors | 311 Klein Ave | Glasgow | 59230 | (406) 228-2496 |

| | | | | | | | | |
|--------------------------|------------------|--------------------------|-------------------------|--|---|--------------------|---|-----------------------------|
| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
| 4 / Currently in Use | 0 | | | | | | <div style="display: flex; justify-content: space-between;"> <div> A B C D E F G H I J K L </div> <div> B D E F G H I J K L </div> </div> | Yes No No No |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Missouri River Outpost 380 Highway 117 Nashua MT 59248 Phone: (406) 526-3231

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|------------------------|-------------------------|---------------|-------|----------------|
| 5304078 | Missouri River Outpost | 380 MT Highway 117 | Nashua | 59248 | (406) 228-3645 |

| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection | Piping Release Detection | FR Met |
|----------------------------|-----------|---------------------|--------------------|---|---|--------------|--|--|--------------------|
| Status | | | | | | | | | Spill/Overl/C |
| 3 / 03 Currently In Use | 4367 | 6/1/1999 07 / No | Gasoline 12,000 | Polyethylene Tank Jacket Double-Walled | Galvanized Steel Double-Walled/Non-Corro | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Farmers Union Oil Co PO Box 108 Nashua MT 59248 Phone: (406) 746-3311

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------------------|-------------------------|---------------|-------|----------------|
| 5310461 | Farmers Union Oil Co Nashua | 810 Main St | Nashua | 59248 | (406) 746-3311 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|--|---------------------------------------|--------------|--|-------------------------|
| 5 / 05 Currently in Use | 937 | 3/1/1990 16 / No | Diesel 2,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 6 / 06 Currently in Use | 938 | 3/1/1990 16 / No | Gasoline 4,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently in Use | 939 | 3/1/1990 16 / No | Diesel 4,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |
| 8 / 08 Currently in Use | 940 | 3/1/1990 16 / No | Gasoline 4,000 | STI-P3 None | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F G H I <input checked="" type="radio"/> K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Burlington Northern Railroad 235 Main St Havre MT 59501 Phone: (406) 265-0483

| | | | | | |
|------------------|------------------------------------|--------------------------------|----------------------|------------|-----------------------|
| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
| 6015036 | Former Valco Agri Service Elevator | Front Street | Nashua | 59248 | |

| | | | | | | | | |
|----------------------------|------------------|--------------------------|-------------------------|--|---|--------------------|--|-----------------------------|
| TankID/Alt TankID | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
| 1 / 01 Currently in Use | 0 | | Heating Oil 500 | Asphalt Coated or Bare Steel None | No Piping None | Not Listed | <div style="display: flex; flex-wrap: wrap; padding: 2px;"> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">A</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">B</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">C</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">D</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">E</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">F</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">G</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">H</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">I</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">J</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">K</div> <div style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 2px;">L</div> </div> | Yes No No No |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Pro Coop PO Box 167 Opheim MT 59250 Phone: (406) 762-3231

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|-----------------|-------------------------|---------------|-------|----------------|
| 5307814 | Pro Coop Opheim | 45th & Main St | Opheim | 59250 | (406) 762-3231 |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|-------------------|--|---------------------------------------|--------------|--|-------------------------|
| 1 / 05 Currently in Use | 1821 | 8/1/1993 12 / No | Gasohol 3,700 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 2 / 06 Currently in Use | 1822 | 8/1/1993 12 / No | Diesel 2,300 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 3 / 04 Currently in Use | 1820 | 8/1/1993 12 / No | Gasoline 2,300 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |
| 7 / 07 Currently in Use | 1823 | 8/1/1993 12 / No | Diesel 3,700 | Polyethylene Tank Jacket Double-Walled | Fiberglass Reinforced Plastic None | Safe Suction | <div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |

Summary of Facility Information in the County of Valley

Owner Name and Address: Montana Aviation Research Co PO Box 831 Glasgow MT 59230 Phone: (406) 524-3777

| Sys Fac I | Location Name | Location Street Address | Location City | Zip | Location Phone |
|-----------|---------------------------------------|-------------------------|---------------|-------|----------------|
| 5312774 | MT Aviation Research Bldg Co Bldg 649 | | Saint Marie | 59231 | |

| TankID/Alt TankID Status | Tag Numbe | Installed Age/AST | Product Capacity | Tank Mat'l of Construction Secondary Option | Piping Material Secondary Option | Piping Type | Tank Release Detection Piping Release Detection | FR Met Spill/Overl/C |
|-----------------------------|-----------|---------------------|------------------|--|--|-------------|--|-------------------------|
| 4 / S4 Currently in Use | 2975 | 1/1/1994 12 / Ye | Other 50,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |
| 5 / S5 Currently in Use | 2976 | 1/1/1994 12 / Ye | Other 50,000 | Asphalt Coated or Bare Steel None | Fiberglass Reinforced Plastic Double-Walled | Pressurized | <div> <div>A B C D E F G H I J K L</div> <div>B D E F ● H I J K L</div> </div> | Yes Yes Yes Yes |

Tank/Piping Release Detection Codes

| | | | | | |
|--------------------------------------|----------------------------|---------------------------|---------------------------------------|------------------------|---------------------|
| A Manual Tank Gauging | C Inventory Control | E Vapor Monitoring | G Interstit. Dbl-Wall Monitor | I SIR | K Deferred |
| B Tank/Line Tightness Testing | D ATG/Auto Line LD | F GW Monitoring | H Interstit. Sec. Con. Monitor | J Other Methods | L Not Listed |